Descaling procedure B-serie






Dissolve 100 grams of Renegite in 0.75 litres of hand-warm water (approx. 40 °C). Stir the descaling solution, so that the agent is solved well.




Place an empty filter pan (without filter paper) on the container.




Place the spray head above the container.
















An audible signal sounds and the level blocks flash.


MAN Descale B-Serie (01-2019 / A)


Original document by manufacturer © Copyright Bravilor Bonamat B.V.























Remove the plug from the filling opening for the Renegite solution.

Original document by manufacturer © Copyright Bravilor Bonamat B.V.





Place the funnel in the filling opening. Carefully pour the Renegite solution through the funnel.





The water tank is boiled dry to let the Renegite solution flow through the circulation element.















Empty the container through the tap.


MAN Descale B-Serie (01-2019 / A)

Original document by manufacturer © Copyright Bravilor Bonamat B.V.













Empty the container through the tap.













Original document by manufacturer © Copyright Bravilor Bonamat B.V.











Note: Reference model B5 L/R